



Eliminate Fouling of Radiant Tubes

PROBLEM

An increase in Bridgewall temperature can be a symptom of excessive fouling of the fired heater's radiant tubes. These tubes tend to oxidize under operating conditions.

SOLUTION

Our patented Hot Tube Descaling service removes radiant section process tube fireside soot, scale, and fouling during furnace operation.

8-10
Years of
Protection



Watch Hot Tube
Descaling in action

Benefits



RESTORE PRODUCTION RATES

Average bridgewall temperature reduction of 50°F (10°C) to 100°F (38°C)




ZERO DOWNTIME

Our Hot Tube Descaling Service is performed while the unit is in operation



PREVENT SHUTDOWNS

Prevents asset failure and costly shutdowns



info@integratedglobal.com | integratedglobal.com